

An agency of the Government of Ontario



Un organisme du gouvernement de l'Ontario

This document was retrieved from the Ontario Heritage Act e-Register, which is accessible through the website of the Ontario Heritage Trust at **www.heritagetrust.on.ca**.

Ce document est tiré du registre électronique. tenu aux fins de la *Loi sur le patrimoine de l'Ontario,* accessible à partir du site Web de la Fiducie du patrimoine ontarien sur **www.heritagetrust.on.ca.** 

Registry Division of Essex(12) Part of Lot 14, Concession 2 Geographic Township of Anderdon Now in the Town of Amherstburg, County of Essex, Province of Onrario

All of P.I.N. 01548-0529 (R)

5 4

Area = 4.0 Acres more or less

COMMENCING at a point in the southeastern limit of Riverview Boulevard being a 66' wide road allowance opened by order of the Western District Court of Quarter Sessions, (Dated July 11, 1840) said point also being shown as the northeast corner of Block 'B', Plan M-101;

THENCE northeasterly along the southeast limit of said Riverview Boulevard a distance of 555.25' to a point marking the beginning of a road curve to the right with a radius of 165.92', an arc length of 115.17' and a chord length of 112.92' to a point, said point being in the southern limit of Essex County Road No. 8, (the original road allowance between the Townships of Anderdon and Sandwich West);

THENCE easterly along the last mentioned limit, a distance of 134.33' to a point;

THENCE southerly at right angles to the southern limit of County Road No. 8, a distance of 97.0' to a point;

THENCE easterly on a course parallel to the southern limit of said Essex County Road No. 8, a distance of 13.0' to a point;

THENCE southerly on a course at right angles to the last described limit, a distance of 299.65' to a point;

THENCE westerly a distance of 22.0' more or less to a point shown as the northeast corner of Block 'A', Plan M-102;

THENCE continuing westerly along the northern limit of said Block 'A', Plan M-102 and also along the northern limit of Block 'B', Plan M-101, a distance of 654.44' more or less to the PLACE OF COMMENCEMENT.

SUBJECT TO EASEMENT in favour of Bell Canada over the lands shown as Part 1, Plan 12R-11219 as described in Instrument No. R1150508.

File: 4-24886 November 25, 2008

Prepared from Record Information only

# CORPORATION OF THE TOWN OF AMHERSTBURG

2

### BY-LAW NO. 2003-89

## A by-law to designate property located within the Town of Amherstburg as being of historical and architectural value to the heritage of the Town of Amherstburg

WHEREAS certain lands and buildings located thereon, within the Town of Amherstburg and hereinafter described are deemed to be of historic and architectural significance;

AND WHEREAS in the opinion of the Council of the Corporation of the Town of Amherstburg, it is expedient and desirable to designate the said property to be of historic and architectural significance;

# NOW THEREFORE THE COUNCIL OF THE CORPORATION OF THE TOWN OF AMHERSTBURG ENACTS AS FOLLOWS:

## HEREBY DESIGNATED AS ST. JOSEPH ROMAN CATHOLIC CHURCH 1913

- 1. That the reasons aforesaid, the property and church building on lands within the Town of Amherstburg located on Concession 2 Part Lot 14 and as described in Schedule A attached hereto, which schedule forms part of this By-law, be and the same is hereby proclaimed to be designated in accordance with the provisions of Section 4, Bill 176 of the Ontario Heritage Act and amendments thereto.
- 2. This By-law shall come into force and take effect on the day following the final passing hereof by the Council of the Town of Amherstburg.

Read a first, second and third time and finally passed this 27<sup>th</sup> day of October, 2003.

Certified True Copy of the original document. own of Amherstbur Scallin 

Mayor

aillong

Clerk

C

Bylaw 2003-89 Schedule "A"

# St. Joseph Church - River Canard

3

#### Location:

.

(

. . . . . . . . .

St. Joseph Church is located at the corner of County Road 8 and South Riverview Drive in the Town of Amherstburg.



#### History:

St. Joseph Parish was founded in 1864 by incorporating the extremities of Assumption Parish (Windsor) founded in 1748 and St. John the Baptist Parish (Amherstburg) founded in 1802. St. Joseph Church is situated eleven kilometers from Amherstburg and sixteen kilometers from Windsor. The current Church is the third church on the site, with the first being a small Chapel located approximately where the rectory driveway is now. The first mass was celebrated in October 1864. Six years later in 1870 Father Marseille undertook the construction of the second Church, the first church on the site of the present


(

church. The Church measured eighty feet in length by forty-five in width. A vestibule fifteen feet by twelve feet was in the front and had eight steps leading to this large porch.

In October 1910 a new pastor, Father Loiselle, was appointed to St. Joseph's. The new pastor quickly realized that the Parish had outgrown the existing Church. The first task Father Loiselle undertook was to build a modern rectory - the current one - at a cost of \$7000. He then undertook the construction of a new Church. In the spring of 1911 the first Church was demolished to make way for the new one. Under the direction of Father Loiselle each able-bodied parishioner had to deliver his share of construction materials to the new Church site. Architect J.O. Turgeon of Montreal designed the Church Plans, the brickwork was done by Mr. Joseph Wilson of Amherstburg and the woodwork by Mr. Urgel Jacques of Windsor. The Church measures one hundred and fifty-eight feet long on the outside, one hundred and fifty-three feet long on the inside and sixty eight feet to the roof above the wall plates. On June 15, 1913 His Excellency Mgr. M.F. Fallon blessed the corner stone. The first mass was celebrated in the basement of the Church on Sunday, April 18, 1915. The first mass celebrated in the Church proper was on October 22, 1916 by Mgr. M.F. Fallon D.D. Bishop of London. The cost of building the new Church was \$75,000. The Church is situated on the River Canard and over the years several bridges have been constructed. The first was a wooden bridge, which opened to allow boats through. This was replaced with a steel bridge built in 1906, which in turn was replaced with a cement bridge on September 1937 at a cost of \$30,000. This cement bridge frames the Church as you approach it. The bridge was extensively repaired in 2002.

(

(



(


C

(

St. Joseph Church - View as you come into the Church

Mr. and Mrs. Charles Malczyks, Polish immigrants, redecorated the present interior of the Church in 1953. The paintings took over a year to do and depict seventeen religious scenes. In addition Mr. Austin Meloche, a parishioner of St. Joseph's, constructed walnut altars. Mr. Arthur Schilling of Detroit designed the Church altars. The main altar is 17 feet high while the side altars are 15 and one-half feet in height.

Schedule "A" Bylaw 2003-89



Painting of the Virgin over right side altar

Schedule "A" Bylaw 2003-89

(


C.



C

(

Schedule "A" Bylaw 2003-89



### Schedule A Bylaw 2003-89 Building Inventory Form

9

## Identification

 $\mathcal{C}$ 

C

(

Building Name: St. Joseph Church

Street Location:

9399 Townline Road, Windsor, Ontario, N9J 2W6

County:

Essex

Present Owner: Roman Catholic Episcopal Corporation, Diocese of London

Present Use: Roman Catholic Church

Handicap Access:

Elevator from street level to Church level and basement

.

## Description:

· · · · ·

(

Building Material:	Brick
Structural System:	Masonry load bearing walls
Condition:	Excellent
Integrity:	Original Site
	1864 Chapel constructed on site
	1870 Wood Church Constructed 1911
	Wood Church Demolished
	1912 Corner Stone for existing Church Dedicated 1915 First Mass in Basement of Existing Church
	1916 Current Church Dedicated.
	1937 Cement Bridge constructed over River Canard
	1953 Church Redecorated, ceilings painted with scenes from the
	Bible
	1960s Vatican II changes; the altar is turned facing the people 1970s New
	carpet installed on the altar and steps leading to altar 1990s Rectory partially restored, stain glass windows repaired, side
	entrances rebuilt, front steps tiled, reconciliation room built 2001 East and South outside walls repaired
	2002 North outside wall repaired.

10

Schedule A Bylaw 2003-89

1

(